110

Quality Control

Work Orde Wednesday, June					4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		Pre	et. to	his v	norn	Ille	Page
Revision ID:	D3908-1 Lug Plate, Aft C	Crosstube		Accept					Setup	Start Stop	1 10011161 01	
	6/2/2010	Start Qty: 12.00 Req'd Qty: 12.00		E 1841	Cust Item I Customer:	D:				·		
Approvals:	Process Plan	: mr	Date: 10-6-	Tooling: SPC (Y/N):		ite:			Run	Start Stop		
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Rejo		Reject Number	Insp. Stamp
Draw Nbr D3908	Revis	ion Nbr					·					<i>-</i> .
100 Waterjet		Memo		0.00			·— · · ·	_B	ر <i>۵-</i> 6.	·3_		
FLOW CNC Waterje		Cut as per d Prog Rev:	<u> </u>	0.00							$\overline{}$	

0.00

0.00

1B10-6-3

Deburr as required

QC2- Inspect parts off machine FAI/FAIB

Memo

Dart Aerospace

W/O:		WORK ORDER CHANGES	HANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			

Part No: _______ PAR #: _____ Fault Category: ______ NCR: Yes No DQA: ____ Date: _____

Resolution:		Resolution: QA: N/C Closed: Date: _						
NCR: WORK ORDER NON-CONFORMANCE (NCR)								
0750	Description of NC	Corrective Action Section		n B	Varification			
SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector	
				-				
	STEP	STEP Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Initial Corrective Action Section B Initial Action Description Sign &	WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Initial Action Description Section C Section C	STEP Description of NC Section A Initial Action Description Sign & Verification Approval Chief Eng.	

Item ID:

D3908-1

Wednesday, June 02, 2010 8:11:44 AM

Accept

Setup Start



Revision ID:

Start Date:

Item Name: Lug Plate, Aft Crosstube

6/2/2010

Start Qty: 12.00

Req'd Qty: 12.00



Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 6/2/2010

Process Plan: _____ Date: ____ Tooling:

Date:

Run

Start

Stop

Stop

QC: _____ Date:___

SPC (Y/N):

Date:

Sequence ID/ **Work Center ID**

120

OC

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours**

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Identify as per dwg & Stock Location:_

QC21- Final Inspection - Work Order Release

150

Packaging

Packaging

Memo

0.00

_6.6-_4_

160

QC

0.00

0.00

10 60 600 1

Quality Control

Memo

2		
•	~	•

W/O:			V	VORK ORDER CHAN	IGES					
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				1,						
Part No		PAR #:								
Resolution:			Disposit	ion:	QA: N/C Closed:			Date:		
NCR:			WORK OR	DER NON-CONFORM	MANCE (NCR)			*****	
DATE	STEP	Description of NC			· Voritioati				Approval	Approval
	-	Section A	Initial Chief Eng	Action Description Chief Eng	n ·	Sign & Date	Section	ı C	Chief Eng	QC Inspector
i										
						34,86				
							[

Picklist Print

Wednesday, June 02, 2010 8:11:43 AM

Work Order ID: 59343

D3908-1

Parent Item: Parent Item Name: Lug Plate, Aft Crosstube

Comments:

IPP RevA: new issue DD 09.11.17 verified by:EC

per dwg revB DD 10.04.20 verified by:EC

10.05.27 DD verf:EC

DD verf:EC

IPP Rev:B as

IPP Rev:C as per PC1

IPP Rev:D per ECN10-581 10.05.28

M304S11GA

Purchased

No

100

sf

Start Date: 6/2/2010

Start Qty: 12.00

0.0533

0.673263

B10-6-3

Required Date: 6/2/2010

Required Qty: 12.00

Page 1

304/316 0.125 Sheet

Location MAT

114488

114799

158.8969 30.8969

Loc Qty

128

Loc Code

158.8969



Dart Ae	rospace	Ltd
---------	---------	-----

Dart Ae	rospace	e Ltd				•				Eng / QC Inspector te:
W/O:				WORK ORDER	CHANGES			······································		
DATE	STEP		PROC	CEDURE CHANGE		Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		· .								
Part No	,•		DAR #·	Fault Category:	NCP.	Vaa	No DO		Data	
				Disposition:					Date: Date:	

NCR:	!	WORK ORDER NON-CONFORMANCE (NCR)								
D.47-		Description of NC		Corrective Action Section B	Verification	A				
DATE	STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
			,							

DART AEROSPACE LTD	Work Order:	59343
Description: Luc PLATE AFT CROSSTUBE	Part Number:	D3908-1
Inspection Dwg: D'3908-1 Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Arti	ele 📗	Prototype
--------------	-------	-----------

i	rawing nension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
6	199	1,005001	.131	8	<u> </u>		
Ø	.191	4.665 - 001	192	<i>u</i>	*		
Ø	.257	+ .006001	P2C.	A		ų.	
8	1375	+ ,006001	,315	>			
7	,310	4 .010	,312	4	<u> </u>		
	. 385	4 .010	1383	x			
	، <i>اح</i> ح	41 .010	756	*			
	.469	47 -010	,469	b			
	3.75	4030	3,755	4			
	,65	4L 030	,651	7	ļ		
	,63	th .030	,627	<u>لا</u>			
	1.587	th_ 010	1,587	W	ļ		
	1.588	4/010	1.588	¥-			
	5.46	12 .030	5,458	×			
	3.80	430	3,802	*	ļ	_	
	2,13	430	9.179	8	<u> </u>	 	
	1.313	1.4	1.312	%			
	·375	1 4 4	374	n	ļ		
	٠ 69 ٢	4 010	697	d	ļ		
	11.14		11.144	100	ļ		Ši.s.
	,375	th .010	.374	٧	<u> </u>		
	·750	Y .010	-756	7		<u> </u>	
	185	4- 100	117	×			

			\cap		
Measured by: R		Audited by:	7	Prototype Approval:	N/A
Deter	-6-2	Date:	10/06/03	Date:	N/A

Rev	Date	Change	Revised by	Approved
1664	Date	New Issue	KJ/JLM	
A	L	NEW ISSUE		• •



Dart A	Aeros	pace	Ltd
--------	-------	------	-----

W/O:			WO	RK ORDER CHANG	ES			··-··			
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	,										

Part No:											
Resolution:			Disposition	Disposition: QA			A: N/C Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORMA	NCE	(NCR	R)				
DATE	STEP	STEP Description of NC Section A	· · · · · · · · · · · · · · · · · · ·	Corrective Action Section			Verific	Verification	Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng		Sign & Date		Section C	Chief Eng	QC Inspector	